

Perfect Inspections

5668 N Prospect Ave Fresno CA 93711
Tel: 559 352-6941 Fax: 559 438-8001 Mobile: 559 352-6941 : Owner
www.perfectinspectionstoday.com jerry_schooley@hotmail.com

CONFIDENTIAL INSPECTION REPORT

PREPARED FOR:

Jo Smith

INSPECTION ADDRESS

123 Anywhere St, Fresno, CA 93711

INSPECTION DATE

4/3/2009

REPRESENTED BY:

Big Bob



This report is the exclusive property of the Inspection Company and the client whose name appears herewith, and its use by any unauthorized persons is prohibited.

GENERAL INFORMATION

Inspection Address: 123 Anywhere St, Fresno, CA 93711
Inspection Date: 4/3/2009
Weather: Clear and Dry - Temperature at time of inspection: 60-70 Degrees

Inspected by: Jerry Schooley

Client Information: Jo Smith
123 Anywhere St, Fresno, CA 93711
EMail: jo@yahoo.com

Buyer's Agent: Big Bob
456 Blank St
Fresno, CA 93711
Mobile: 559 123-4567



Structure Type: Wood Frame
Foundation Type: Raised Foundation
Furnished: Yes
Structure Occupied: Yes
Number of Stories: One

Structure Style: California Ranch

Structure Orientation: West

Estimated Year Built: 1985
Unofficial Sq.Ft.: 2018

People on Site At Time of Inspection: Buyer(s)

PLEASE NOTE:

This report is the exclusive property of Perfect Inspections and the client whose name appears herewith, and its use by any unauthorized persons is strictly prohibited.

The observations and opinions expressed within this report are those of Perfect Inspections and supercede any alleged verbal comments. We inspect all of the systems, components, and conditions described in accordance with the standards of the National Association of Certified Home Inspectors, and those that we do not inspect are clearly disclaimed in the contract and/or in the aforementioned standards. However, some components that are inspected and found to be functional may not necessarily appear in the report, simply because we do not wish to waste our client's time by having them read an unnecessarily lengthy report about components that do not need to be serviced.

In accordance with the terms of the contract, the service recommendations that we make in this report should be completed well before the close of escrow by licensed specialists, who may well identify additional defects or recommend some upgrades that could affect your evaluation of the property.

Report File: 123 Anywhere St

SCOPE OF WORK

You have contracted with Perfect Inspections to perform a generalist inspection in accordance with the standards of practice established by the National Association of Certified Home Inspectors, a copy of which is available upon request. Generalist inspections are essentially visual, and distinct from those of specialists, inasmuch as they do not include the use of specialized instruments, the dismantling of equipment, or the sampling of air and inert materials. Consequently, a generalist inspection and the subsequent report will not be as comprehensive, nor as technically exhaustive, as that generated by specialists, and it is not intended to be. The purpose of a generalist inspection is to identify significant defects or adverse conditions that would warrant a specialist evaluation. Therefore, you should be aware of the limitations of this type of inspection, which are clearly indicated in the standards. However, the inspection is not intended to document the type of cosmetic deficiencies that would be apparent to the average person, and certainly not intended to identify insignificant deficiencies. Similarly, we do not inspect for vermin infestation, which is the responsibility of a licensed exterminator.

Most homes built after 1978, are generally assumed to be free of asbestos and many other common environmental contaminants. However, as a courtesy to our clients, we are including some well documented, and therefore public, information about several environmental contaminants that could be of concern to you and your family, all of which we do not have the expertise or the authority to evaluate, such as asbestos, radon, methane, formaldehyde, termites and other wood-destroying organisms, pests and rodents, molds, microbes, bacterial organisms, and electromagnetic radiation, to name some of the more commonplace ones. Nevertheless, we will attempt to alert you to any suspicious substances that would warrant evaluation by a specialist. However, health and safety, and environmental hygiene are deeply personal responsibilities, and you should make sure that you are familiar with any contaminant that could affect your home environment. You can learn more about contaminants that can affect your home from a booklet published by The environmental Protection Agency, which you can read online at www.epa.gov/iaq/pubs/insidest.htm.

Mold is one such contaminant. It is a microorganism that has tiny seeds, or spores, that are spread on the air then land and feed on organic matter. It has been in existence throughout human history, and actually contributes to the life process. It takes many different forms, many of them benign, like mildew. Some characterized as allergens are relatively benign but can provoke allergic reactions among sensitive people, and others characterized as pathogens can have adverse health effects on large segments of the population, such as the very young, the elderly, and people with suppressed immune systems. However, there are less common molds that are called toxigens that represent a serious health threat. All molds flourish in the presence of moisture, and we make a concerted effort to look for any evidence of it wherever there could be a water source, including that from condensation. Interestingly, the molds that commonly appear on ceramic tiles in bathrooms do not usually constitute a health threat, but they should be removed. However, some visibly similar molds that form on cellulose materials, such as on drywall, plaster, and wood, are potentially toxigenic. If mold is to be found anywhere within a home, it will likely be in the area of tubs, showers, toilets, sinks, water heaters, evaporator coils, inside attics with unvented bathroom exhaust fans, and return-air compartments that draw outside air, all of which are areas that we inspect very conscientiously. Nevertheless, mold can appear as though spontaneously at any time, so you should be prepared to monitor your home, and particularly those areas that we identified. Naturally, it is equally important to maintain clean air-supply ducts and to change filters as soon as they become soiled, because contaminated ducts are a common breeding ground for dust mites, rust, and other contaminants. Regardless, although some mold-like substances may be visually identified, the specific identification of molds can only be determined by specialists and laboratory analysis, and is absolutely beyond the scope of our inspection. Nonetheless, as a prudent investment in environmental hygiene, we categorically recommend that you have your home tested for the presence of any such contaminants, and particularly if you or any member of your family suffers from allergies or asthma. Also, you can learn more about mold from an Environmental Protection Agency document entitled "A Brief Guide to Mold, Moisture and Your Home," by visiting their web site at: <http://www.epa.gov/iaq/molds/moldguide.html/>, from which it can be downloaded.

Asbestos is a notorious contaminant that could be present in any home built before 1978. It is a naturally occurring mineral fiber that was first used by the Greek and Romans in the first century, and it has been widely used throughout the modern world in a variety of thermal insulators, including those in the form of paper wraps, bats, blocks, and blankets. However, it can also be found in a wide variety of other products too numerous to

mention, including duct insulation and acoustical materials, plasters, siding, floor tiles, heat vents, and roofing products. Although perhaps recognized as being present in some documented forms, asbestos can only be specifically identified by laboratory analysis. The most common asbestos fiber that exists in residential products is chrysotile, which belongs to the serpentine or white-asbestos group, and was used in the clutches and brake shoes of automobiles for many years. However, a single asbestos fiber is said to be able to cause cancer, and is therefore a potential health threat and a litigious issue. Significantly, asbestos fibers are only dangerous when they are released into the air and inhaled, and for this reason authorities such as the Environmental Protection Agency [EPA] and the Consumer Product Safety Commission [CPSC] distinguish between asbestos that is in good condition, or non-friable, and that which is in poor condition, or friable, which means that its fibers could be easily crumbled and become airborne. However, we are not specialists and, regardless of the condition of any real or suspected asbestos-containing material [ACM], we would not endorse it and recommend having it evaluated by a specialist.

Radon is a gas that results from the natural decay of radioactive materials within the soil, and is purported to be the second leading cause of lung cancer in the United States. The gas is able to enter homes through the voids around pipes in concrete floors or through the floorboards of poorly ventilated crawlspaces, and particularly when the ground is wet and the gas cannot easily escape through the soil and be dispersed into the atmosphere. However, it cannot be detected by the senses, and its existence can only be determined by sophisticated instruments and laboratory analysis, which is completely beyond the scope of our service. However, you can learn more about radon and other environmental contaminants and their affects on health, by contacting the Environmental Protection Agency (EPA), at www.epa.gov/radon/images/hmbuygud.pdf, and it would be prudent for you to enquire about any high radon readings that might be prevalent in the general area surrounding your home.

Lead poses an equally serious health threat. In the 1920's, it was commonly found in many plumbing systems. In fact, the word "plumbing" is derived from the Latin word "plumbum," which means lead. When in use as a component of a waste system, it is not an immediate health threat, but as a component of potable water pipes it is a definite health-hazard. Although rarely found in modern use, lead could be present in any home build as recently as the nineteen forties. For instance, lead was an active ingredient in many household paints, which can be released in the process of sanding, and even be ingested by small children and animals chewing on painted surfaces. Fortunately, the lead in painted surfaces can be detected by industrial hygienists using sophisticated instruments, but testing for it is not cheap. There are other environmental contaminants, some of which we have already mentioned, and others that may be relatively benign. However, we are not environmental hygienists, and as we stated earlier we disclaim any responsibility for testing or establishing the presence of any environmental contaminant, and recommend that you schedule whatever specialist inspections that may deem prudent within the contingency period.

Perfect Inspections

5668 N Prospect Ave Fresno CA 93711
Tel: 559 352-6941 Fax: 559 438-8001 Mobile: 559 352-6941
Email Address: jerry_schooley@hotmail.com

INVOICE

4/9/09

Client:

Jo Smith
123 Anywhere St
Fresno, CA. 93711

Client's Agent:

Big Bob

456 Blank St
Fresno, CA. 93711

Inspection Address:

123 Anywhere St
Fresno, CA. 93711

Inspection Date/Time:

4/3/2009

Total Due: \$ 0.00

PAID IN FULL -
Thanks for your business

The inspection is subject to the terms as agreed upon in the contract executed between the parties. This inspection contract and the inspection report do not constitute a home warranty or guarantee whatsoever.

Perfect Inspections and Energy Consulting

Exterior

With the exception of townhomes, condominiums, and residences that are part of a planned urban development, or PUD, we evaluate the following exterior features: driveways, walkways, fences, gates, handrails, guardrails, yard walls, carports, patio covers, decks, building walls, fascia and trim, balconies, doors, windows, lights, and outlets. However, we do not evaluate any detached structures, such as storage sheds and stables, and we do not water test or evaluate subterranean drainage systems or any mechanical or remotely controlled components, such as driveway gates. Also, we do not evaluate landscape components, such as trees, shrubs, fountains, ponds, statuary, pottery, fire pits, patio fans, heat lamps, and decorative or low-voltage lighting. In addition, we do not comment on coatings or cosmetic deficiencies and the wear and tear associated with the passage of time, which would be apparent to the average person. However, cracks in hard surfaces can imply the presence of expansive soils that can result in continuous movement, but this could only be confirmed by a geological evaluation of the soil.

Grading & Drainage

General Comments

Informational Conditions

Water can be destructive and foster conditions that are deleterious to health. For this reason, the ideal property will have soils that slope away from the residence and the interior floors will be several inches higher than the exterior grade. Also, the residence will have roof gutters and downspouts that discharge into area drains with catch basins that carry water away to hard surfaces. However, we cannot guarantee the condition of any subterranean drainage system, but if a property does not meet this ideal, or if any portion of the interior floor is below the exterior grade, we cannot endorse it and recommend that you consult with a grading and drainage contractor, even though there may not be any evidence of moisture intrusion. The sellers or occupants will obviously have a more intimate knowledge of the site than we could possibly hope to have during our limited visit, however we have confirmed moisture intrusion in residences when it was raining that would not have been apparent otherwise. Also, in conjunction with the cellulose material found in most modern homes, moisture can facilitate the growth of biological organisms that can compromise building materials and produce mold-like substances that can have an adverse affect on health.

Interior-Exterior Elevations

Informational Conditions

There is an adequate difference in elevation between the exterior grade and the interior floors that should ensure that moisture intrusion would not threaten the living space, but of course we cannot guarantee that.

Drainage Mode

Informational Conditions

Drainage is facilitated by soil percolation hard surfaces, area drains, and full or partial gutters, and we did not observe any evidence of moisture threatening the living space. However, the area drains must be kept clean or moisture intrusion could result.

Components and Conditions Needing Service

There are areas where water will be directed toward the house instead of away from it, as recommended. This not only allows for the possibility of moisture intrusion but also differential settling, et cetera. Side yard of house should be graded away from house.

Inspection Address: 123 Anywhere St, Fresno, CA 93711
Inspection Date/Time: 4/3/2009

There are areas where water is directed toward the house instead of away from it - *Continued*



House Wall Finish

House Wall Finish Type

Informational Conditions

The house walls are finished with stucco.

House Wall Finish Observations

Informational Conditions

The house wall finish is in acceptable condition.

Exterior Components

General Comments

Informational Conditions

It is important to maintain a property, including painting or sealing walkways, decks, and other hard surfaces, and it is particularly important to keep the house walls sealed, which provide the only barrier against deterioration. Unsealed cracks around windows, doors, and thresholds can permit moisture intrusion, which is the principle cause of the deterioration of any surface. Unfortunately, the evidence of such intrusion may only be obvious when it is raining. We have discovered leaking windows while it was raining that may not have been apparent otherwise. Regardless, there are many styles of windows but only two basic types, single and dual-glazed. Dual-glazed windows are superior, because they provide a thermal as well as an acoustical barrier. However, the hermetic seals on these windows can fail at any time, and cause condensation to form between the panes. Unfortunately, this is not always apparent, which is why we disclaim an evaluation of hermetic seals. Nevertheless, in accordance with industry standards, we test a representative number of unobstructed windows, and ensure that at least one window in every bedroom is operable and facilitates an emergency exit.

Driveways

Informational Conditions

The driveway is in acceptable condition.

Walkways

Informational Conditions

The walkways are in acceptable condition.

Fences & Gates

Informational Conditions

The fences and gates are serviceable, and would not need service at this time.

Fascia & Trim

Informational Conditions

The fascia board and trim are in acceptable condition.

Exterior Wooden Doors

Informational Conditions

The exterior doors are in acceptable condition.

Porches or Stoops

Informational Conditions

The porch and stoops are in acceptable condition.

Windows

Informational Conditions

The windows are in acceptable condition. However, in accordance with industry standards, we do not test every window in the house, and particularly if the house is furnished. We do test every unobstructed window in every bedroom to ensure that at least one facilitates an emergency exit.

Outlets

Informational Conditions

The outlets that were tested are functional and include ground-fault protection.

Lights

Informational Conditions

The lights outside the doors of the residence are functional. However, we do not inspect or evaluate decorative lights.

Structural

All structures are dependent on the soil beneath them for support, but soils are not uniform. Some that might appear to be firm and solid can liquefy and become unstable during seismic activity. Also, there are soils that can expand to twice their volume with the influx of water and move structures with relative ease, raising and lowering them and fracturing slabs and other hard surfaces. In fact, expansive soils have accounted for more structural damage than most natural disasters. Regardless, foundations are not uniform, and conform to the structural standard of the year in which they were built. In accordance with our standards of practice, we identify foundation types and look for any evidence of structural deficiencies. However, cracks or deteriorated surfaces in foundations are quite common. In fact, it would be rare to find a raised foundation wall that was not cracked or deteriorated in some way, or a slab foundation that did not include some cracks concealed beneath the carpeting and padding. Fortunately, most of these cracks are related to the curing process or to common settling, including some wide ones called cold-joint separations that typically contour the footings, but others can be more structurally significant and reveal the presence of expansive soils that can predicate more or less continual movement. We will certainly alert you to any suspicious cracks if they are clearly visible. However, we are not specialists, and in the absence of any major defects we may not recommend that you consult with a foundation contractor, a structural engineer, or a geologist, but this should not deter you from seeking the opinion of any such expert.

Various Hard Surfaces

Common Observations

Informational Conditions

The visible portions of the hard surfaces, such as the house walls, yard walls, concrete decks, and walkways, are in acceptable condition. However, such surfaces are subject to damage caused by soil movement, etc.

Structural Elements

Identification of Wall Structure

Informational Conditions

The walls are conventionally framed with wooden studs.

Identification of Floor Structure

Informational Conditions

The floor structure consists of posts piers girders and joists sheathed with plywood or diagonal boards.

Identification of Ceiling Structure

Informational Conditions

The ceiling structure consists of standard joists.

Identification of Roof Structure

Informational Conditions

The roof structure is conventionally framed with rafters, purlins, collar-ties, et cetera.

Raised Foundation

General Comments

Informational Conditions

This residence has a raised foundation. Such foundations permit access, and provide a convenient area for the distribution of water pipes, drain pipes, vent pipes, electrical conduits, and ducts. However, although raised foundations are far from uniform, most include concrete footings and walls that extend above the ground with anchor bolts that hold the house onto the foundation, but the size and spacing of the bolts vary. In the absence of major defects, most structural engineers agree that the one critical issue with raised foundations is that they should be bolted. Our inspection of these foundations conforms to industry standards, which is that of a generalist and not a specialist, and we do not use any specialized instruments to establish that the structure is level. We typically enter all accessible areas, to confirm that foundations are bolted and to look for any evidence of structural deformation or damage, but we may not comment on minor deficiencies, such as on commonplace settling cracks in the stem walls and slight deviations from plumb and level in the intermediate floor framing, which would have little structural significance. Interestingly, there is no absolute standard for evaluating cracks, but those that are less than ¼" and which do not exhibit any vertical or horizontal displacement are generally not regarded as being structurally relevant. Nevertheless, all others should be evaluated by a specialist. However, in the absence of any major defects, we may not recommend that you consult with a foundation contractor, a structural engineer, or a geologist, but this should not deter you from seeking the opinion of any such expert.

Raised Foundation Type

Informational Conditions

The foundation is raised and bolted to the standards of the year in which it was constructed, which may well be adequate but which would not meet current structural standards.

Method of Evaluation

Informational Conditions

We evaluated the raised foundation by accessing and evaluating the components within the crawlspace.

Crawlspace Observations

Informational Conditions

The crawlspace is accessible and in acceptable condition.

Intermediate Floor Framing

Informational Conditions

The intermediate floor framing is in acceptable condition. There may be some deviations from plumb, level, etc, but none that would have any serious structural significance.

Electrical

Informational Conditions

The electrical components that are visible within the crawlspace appear to be in acceptable condition.

Ventilation

Informational Conditions

The ventilation in the foundation crawlspace appears to be standard and adequate.

Floor Insulation

Informational Conditions

There is no floor insulation, which would not have been required when this residence was constructed.

Roof/Attic

There are many different roof types, which we evaluate by walking on their surfaces. If we are unable or unwilling to do this for any reason, we will indicate the method that was used to evaluate them. Every roof will wear differently relative to its age, the number of its layers, the quality of its material, the method of its application, its exposure to direct sunlight or other prevalent weather conditions, and the regularity of its maintenance. Regardless of its design-life, every roof is only as good as the waterproof membrane beneath it, which is concealed and cannot be examined without removing the roof material, and this is equally true of almost all roofs. In fact, the material on the majority of pitched roofs is not designed to be waterproof only water-resistant. However, what remains true of all roofs is that, whereas their condition can be evaluated, it is virtually impossible for anyone to detect a leak except as it is occurring or by specific water tests, which are beyond the scope of our service. Even water stains on ceilings, or on the framing within attics, could be old and will not necessarily confirm an active leak without some corroborative evidence, and such evidence can be deliberately concealed. Consequently, only the installers can credibly guarantee that a roof will not leak, and they do. We evaluate every roof conscientiously, and even attempt to approximate its age, but we will not predict its remaining life expectancy, or guarantee that it will not leak. Naturally, the sellers or the occupants of a residence will generally have the most intimate knowledge of the roof and of its history. Therefore, we recommend that you ask the sellers about it, and that you either include comprehensive roof coverage in your home insurance policy, or that you obtain a roof certification from an established local roofing company.

Wood Roof

General Observation

Components and Conditions Needing Service

The roof looks to be the original roof and appears to have been previously repaired



Method of Evaluation

Informational Conditions

We evaluated the roof and its components by walking on its surface.

Estimated Age

Informational Conditions

The roof appears to be the same age as the residence, or approximately 25-30 years old.

Roofing Material

Components and Conditions Needing Service

The roof needs to be serviced for the following reasons: Because the roof is the original wood shingle and may be 25-30 years old there is obvious deficiencies. This service should be scheduled well before the close of escrow, because additional defects could be revealed by a specialist, and our service does not include any guarantee against leaks. For a guarantee, a roofing company would have to perform a water-test and issue a roof certification.

Flashings

Informational Conditions

The roof flashings are in acceptable condition.

Gutters & Drainage

Functional Components and Conditions

The gutters appear to be in acceptable condition. However, without water in them it is difficult to judge whether they are correctly pitched to direct water into the downspouts, but they should function as they were intended.

Chimney

The Chimney Safety Institute of America has published industry standards for the inspection of chimneys, and on January 13, 2000, the National Fire Protection Association adopted these standards as code, known as NFPA 211. Our inspection of masonry and factory-built chimneys to what is known as a Level-One inspection, which is purely visual and not to be confused with Level-Two, and Level-Three inspections, which are performed by qualified specialists with a knowledge of codes and standards, and typically involves dismantling components and/or investigations with video-scan equipment and other means to evaluate chimneys.

Family Room Chimney

Common Observations

Informational Conditions

We do not inspect or evaluate chimneys, flues or vent systems

General Unlined Masonry

Components and Conditions Needing Service

Unlined chimneys, or those without flue liners, are suspect. Although such flues include a plaster coat of mortar, the corrosive effect of flue gases and the elements can deteriorate the mortar. In fact, the Chimney Safety Institute of America reported in 1992 that "all unlined chimneys, irrespective of fuel used, are very liable to become defective through disintegration of the mortar joints." However, we recommend a level-two inspection by a qualified specialist within the contingency period or before the close of escrow, as recommended by NAPA standards "upon the sale or transfer of a property."

Weather Cap-Spark Arrestor

Functional Components and Conditions

The chimney does not have a weather cap/spark arrestor, which is recommended.



Crown or Termination Cap

Informational Conditions

The crown, which is designed to seal the chimney wall and to shed rainwater and thereby prevent moisture from deteriorating the chimney, is in acceptable condition.

Chimney Flashings

Informational Conditions

The chimney flashings are in acceptable condition.

Damper

Functional Components and Conditions

The damper is functional.

Fireplace

Informational Conditions

The fireplace is in acceptable condition.

Ash Box

Informational Conditions

The ash box is functional, and should be kept clear and clean.

Hearth

Informational Conditions

The hearth is in acceptable condition.

Mantle

Informational Conditions

The fireplace mantle is in acceptable condition.

Chimney Flue

Informational Conditions

We do not inspect chimney flue or vent systems

Plumbing

Plumbing systems have common components, but they are not uniform. In addition to fixtures, these components include gas pipes, water pipes, pressure regulators, pressure relief valves, shut-off valves, drain and vent pipes, and water-heating devices, some of which we do not test if they are not in daily use. The best and most dependable water pipes are copper, because they are not subject to the build-up of minerals that bond within galvanized pipes, and gradually restrict their inner diameter and reduce water volume. Water softeners can remove most of these minerals, but not once they are bonded within the pipes, for which there would be no remedy other than a re-pipe. The water pressure within pipes is commonly confused with water volume, but whereas high water volume is good high water pressure is not. In fact, whenever the street pressure exceeds eighty pounds per square inch a regulator is recommended, which typically comes factory preset between forty-five and sixty-five pounds per square inch. However, regardless of the pressure, leaks will occur in any system, and particularly in one with older galvanized pipes, or one in which the regulator fails and high pressure begins to stress the washers and diaphragms within the various components.

Waste and drainpipes pipes are equally varied, and range from modern ABS ones [acrylonitrile butadiene styrene] to older ones made of cast-iron, galvanized steel, clay, and even a cardboard-like material that is coated with tar. The condition of these pipes is usually directly related to their age. Older ones are subject to damage through decay and root movement, whereas the more modern ABS ones are virtually impervious to damage, although some rare batches have been alleged to be defective. However, inasmuch as significant portions of drainpipes are concealed, we can only infer their condition by observing the draw at drains. Nonetheless, blockages will occur in the life of any system, but blockages in drainpipes, and particularly in main drainpipes, can be expensive to repair, and for this reason we recommend having them video-scanned. This could also confirm that the house is connected to the public sewer system, which is important because all private systems must be evaluated by specialists.

Potable Water Supply Pipes

Water Main Shut-off Location

Informational Conditions

The main water shut-off valve is located at the front of the residence.

Galvanized Water Pipes

Informational Conditions

The potable water pipes within this residence are galvanized, and assumed to be original. They appear to be in acceptable condition. However, they may produce rusty looking water from time to time and, because the water volume in such pipes will gradually be reduced by a build-up of minerals within them, we do not endorse them.

General Gas Components

Gas Main Shut-Off Location

Informational Conditions

The gas main shut-off is located in the side yard.

Gas Main Observations

Functional Components and Conditions

The gas is provided by public gas service PG&E and appears to be functional

Gas Supply Pipes

Informational Conditions

The visible portions of the gas pipes appear to be in acceptable condition.

Gas Water Heaters

General Comments

Informational Conditions

There are a wide variety of residential water heaters that range in capacity from fifteen to one hundred gallons. They can be expected to last at least as long as their warranty, or from five to eight years, but they will generally last longer. However, few of them last longer than fifteen or twenty years and many eventually leak. So it is always wise to have them installed over a drain pan plumbed to the exterior. Also, it is prudent to flush them annually to remove minerals that include the calcium chloride bi-product of many water softening systems. The water temperature should be set at a minimum of 110 degrees fahrenheit to kill microbes and a maximum of 140 degrees to prevent scalding. Also, water heaters can be dangerous if they are not seismically secured and equipped with either a pressure/temperature relief valve and discharge pipe plumbed to the exterior, or a Watts 210 gas shut-off valve.

Age Capacity & Location

Informational Conditions

Hot water is provided by a newer, 40 gallon water heater that is located in the laundry room.

Common Observations

Functional Components and Conditions

The water heater appears to be functional but could use a insulating blanket

Water Shut-Off Valve & Connectors

Informational Conditions

The shut-off valve and water connectors are functional.

Gas Shut-Off Valve & Connector

Informational Conditions

The gas control valve and its connector at the water heater are functional.

Vent Pipe & Cap

Informational Conditions

The vent pipe and cap appear to be functional.

Relief Valve & Discharge Pipe

Functional Components and Conditions

The water heater is equipped with a mandated pressure-temperature relief valve.

Drain Valve

Informational Conditions

The drain valve is in place and presumed to be functional.

Drain Pan & Discharge Pipe

Functional Components and Conditions

The water heater inside the house does not have a drain pan and is recommended



Seismic Straps

Informational Conditions

The water heater is seismically secured.

Waste & Drainage Systems

General Comments

Informational Conditions

We attempt to evaluate drain pipes by flushing every drain that has an active fixture while observing its draw and watching for blockages or slow drains, but this is not a conclusive test and only a video-scan of the main line would confirm its actual condition. However, you can be sure that blockages will occur, usually relative in severity to the age of the system, and will range from minor ones in the branch lines, or at the traps beneath sinks, tubs, and showers, to major blockages in the main line. The minor ones are easily cleared, either by chemical means or by removing and cleaning the traps. However, if tree roots grow into the main drain that connects the house to the public sewer, repairs could become expensive and might include replacing the entire main line. For these reasons, we recommend that you ask the sellers if they have ever experienced any drainage problems, or you may wish to have the main waste line video-scanned before the close of escrow. Failing this, you should obtain an insurance policy that covers blockages and damage to the main line. However, most policies only cover plumbing repairs within the house, or the cost of roofer service, most of which are relatively inexpensive.

Type of Material

Informational Conditions

The visible portions of the drainpipes are an older cast-iron type, which are not as dependable as modern ABS drainpipes.

Drain Waste & Vent Pipes

Informational Conditions

Based on industry recommended water tests, the drainpipes are functional at this time. However, only a video-scan of the main drainpipe could confirm its actual condition.

Electrical

There are a wide variety of electrical systems with an even greater variety of components, and any one particular system may not conform to current standards or provide the same degree of service and safety. What is most significant about electrical systems however is that the national electrical code [NEC] is not retroactive, and therefore many residential systems do not comply with the latest safety standards. Regardless, we are not electricians and in compliance with our standards of practice we only test a representative number of switches and outlets and do not perform load-calculations to determine if the supply meets the demand. However, in the interests of safety, we regard every electrical deficiency and recommended upgrade as a latent hazard that should be serviced as soon as possible, and that the entire system be evaluated and certified as safe by an electrician. Therefore, it is essential that any recommendations that we may make for service or upgrades should be completed before the close of escrow, because an electrician could reveal additional deficiencies or recommend some upgrades for which we would disclaim any further responsibility. However, we typically recommend upgrading outlets to have ground fault protection, which is a relatively inexpensive but essential safety feature. These outlets are often referred to as GFCI's, or ground fault circuit interrupters and, generally speaking, have been required in specific locations for more than thirty years, beginning with swimming pools and exterior outlets in 1971, and the list has been added to ever since: bathrooms in 1975, garages in 1978, spas and hot tubs in 1981, hydro tubs, massage equipment, boat houses, kitchens, and unfinished basements in 1987, crawlspaces in 1990, wet bars in 1993, and all kitchen countertop outlets with the exception of refrigerator and freezer outlets since 1996. Similarly, AFCI's or arc fault circuit interrupters, represent the very latest in circuit breaker technology, and have been required in all bedroom circuits since 2002. However, inasmuch as arc faults cause thousands of electrical fires and hundreds of deaths each year, we categorically recommend installing them at every circuit as a prudent safety feature.

Main Panel

General Comments

Informational Conditions

National safety standards require electrical panels to be weatherproof, readily accessible, and have a minimum of thirty-six inches of clear space in front of them for service. Also, they should have a main disconnect, and each circuit within the panel should be clearly labeled. Industry standards only require us to test a representative number of accessible switches, receptacles, and light fixtures. However, we attempt to test every one that is unobstructed, but if a residence is furnished we will obviously not be able to test each one.

Service Entrance

Informational Conditions

The main conductor lines are underground, or part of a lateral service entrance. This is characteristic of modern electrical services but, inasmuch as the service lines are underground and cannot be seen, they are not evaluated as part of our service.

Panel Size & Location

Informational Conditions

The residence is served by a 200 amp, 220 volt panel, located in the house side yard.


Main Panel Observations

Informational Conditions

Various circuits within the panel are not labeled but should be, so that the appropriate load calculations and breaker sizes could be determined.

Inspection Address: 123 Anywhere St, Fresno, CA 93711
Inspection Date/Time: 4/3/2009

Various circuits within the panel are not labeled but should be - *Continued*



Panel Cover Observations

Informational Conditions

The exterior panel cover is in acceptable condition.

The interior panel cover is in acceptable condition.

Wiring Observations

Informational Conditions

The visible portions of the wiring has no visible deficiencies.

Circuit Breakers

Informational Conditions

There are no visible deficiencies with the circuit breakers.

Components and Conditions Needing Service

Various circuits are not labeled, which is recommended.

Grounding

Informational Conditions

The panel is grounded to a water pipe. Current standards require the panel to be double-grounded, and you may wish to consider having this done as a safety upgrade. However, such an upgrade is not currently mandated.

Heat and Air Conditioning

The components of most heating and air-conditioning systems have a design-life ranging from ten to twenty years, but can fail prematurely with poor maintenance, which is why we apprise you of their age whenever possible. We test and evaluate them in accordance with the standards of practice, which means that we do not dismantle and inspect the concealed portions of evaporator and condensing coils, the heat exchanger, which is also known as the firebox, electronic air-cleaners, humidifiers, ducts and in-line duct-motors or dampers. We perform a conscientious evaluation of both systems, but we are not specialists. However, even the most modern heating systems can produce carbon monoxide, which in a sealed or poorly ventilated room can result in sickness, debilitating injury, and even death. Therefore, in accordance with the terms of our contract, it is essential that any recommendations that we make for service or a second opinion be scheduled before the close of escrow, because a specialist could reveal additional defects or recommend further upgrades that could affect your evaluation of the property, and our service does not include any form of warranty or guarantee.

HVAC Package Systems

Age & Location

Informational Conditions

Central heat and air-conditioning are provided by a newer package system that is located on roof.



Common Observations

Informational Conditions

The package-system is newer and functional. Such systems are designed to last approximately twenty years, but they should be serviced bi-annually and have their filters changed every two to three months.

Furnace

Informational Conditions

The furnace is functional.

Circulating Fan

Informational Conditions

The circulating fan is clean and functional.

Gas Valve & Connector

Informational Conditions

The gas valve and connector are in acceptable condition.

Return-Air Compartment

Informational Conditions

The return-air compartment is in acceptable condition.

Condensate Drainpipe

Informational Conditions

The condensate drainpipe discharges into a common roof vent.

Differential Temperature Readings

Informational Conditions

The air-conditioning responded and achieved an acceptable differential temperature split between the air entering the system and that coming out, of eighteen degrees or more.

Thermostats

Functional Components and Conditions

The thermostat was tested and produced heating and cooling as designed

Registers

Informational Conditions

The registers are reasonably clean and functional.

Flexible Ducting

Informational Conditions

The ducts have no visible deficiencies. They are a modern flexible type that are comprised of an outer plastic sleeve and a clear inner liner that contains fiberglass insulation.

Stand Mounting and Hardware

Functional Components and Conditions

The stand mounting and hardware are in acceptable condition

Living Areas

Our inspection of living space includes the visually accessible areas of walls, floors, cabinets and closets, and includes the testing of a representative number of windows and doors, switches and outlets. However, we do not evaluate window treatments, or move furniture, lift carpets or rugs, empty closets or cabinets, and we do not comment on cosmetic deficiencies. We may not comment on the cracks that appear around windows and doors, or which follow the lines of framing members and the seams of drywall and plasterboard. These cracks are a consequence of movement, such as wood shrinkage, common settling, and seismic activity, and will often reappear if they are not correctly repaired. Such cracks can become the subject of disputes, and are therefore best evaluated by a specialist. Similarly, there are a number of environmental pollutants that we have already elaborated upon, the specific identification of which is beyond the scope of our service but which can become equally contentious. In addition, there are a host of lesser contaminants, such as that from moisture penetrating carpet-covered cracks in floor slabs, as well as odors from household pets and cigarette smoke that can permeate walls, carpets, heating and air conditioning ducts, and other porous surfaces, and which can be difficult to eradicate. However, inasmuch as the sense of smell adjusts rapidly, and the sensitivity to such odors is certainly not uniform, we recommend that you make this determination for yourself, and particularly if you or any member of your family suffers from allergies or asthma, and then schedule whatever remedial services may be deemed necessary before the close of escrow.

Indoor Environmental Issues

Environmental Observations

Informational Conditions

We do not test for mold or measure indoor air quality, which the Consumer Product safety Commission ranks fifth among potential contaminants. Regardless, a person's health is a truly personal responsibility, and inasmuch as we not inspect for mold or test for other environmental contaminants we recommend that you schedule an inspection by an environmental hygienist before the close of escrow. And this would be imperative if you or any member of your family suffers from allergies or asthma, and could require the sanitizing of air ducts and other concealed areas.

Note: Mold cannot exist without moisture. Therefore, any moisture whatsoever, whether it be from inadequate grading and drainage, a leaking roof, window, or door, or moisture from a faulty exhaust vent, a condensate pipe, an evaporator coil, or a component of a plumbing system should be serviced immediately, or the potential for mold infestation will remain.

Main Entry

Furnished Residence Comment

Informational Conditions

The residence is furnished, and in accordance with industry standards we only inspect those surfaces that are exposed and readily accessible. We do not move furniture, lift carpets, nor remove or rearrange items within closets and cabinets.

No Recommended Service

Informational Conditions

We have evaluated the entry, and found it to be in acceptable condition.

Living Room

No Recommended Service

Informational Conditions

We have evaluated the living room windows, flooring, ceiling, walls and electrical outlets, and found all components to be in acceptable condition.

Family Room

No Recommended Service

Informational Conditions

We have evaluated the family room windows, flooring, ceiling, walls and electrical outlets, and found all components to be in acceptable condition.

Kitchen

We test kitchen appliances for their functionality, and cannot evaluate them for their performance nor for the variety of their settings or cycles. However, if they are older than ten years, they may well exhibit decreased efficiency. Also, many older gas and electric ranges are not secured and can be easily tipped, particularly when any weight is applied to an open range door, and all such appliances should be confirmed to be secure. Regardless, we do not inspect the following items: free-standing appliances, refrigerators, trash-compactors, built-in toasters, coffee-makers, can-openers, blenders, instant hot-water dispensers, water-purifiers, barbecues, grills or rotisseries, timers, clocks, thermostats, the self-cleaning capability of ovens, and concealed or countertop lighting, which is convenient but often installed after the initial construction and not wired to national electrical standards.

Kitchen

Doors

Informational Conditions

The doors are functional.

Flooring

Informational Conditions

The floor has no significant defects.

Walls & Ceiling

Functional Components and Conditions

The walls and ceiling are in acceptable condition.

Dual-Glazed Windows

Functional Components and Conditions

The window is functional.

Sink & Countertop

Informational Conditions

The counter top has typical cosmetic damage, which would not necessarily need to be serviced.

Cabinets

Informational Conditions

The cabinets have typical, cosmetic damage, or that which is commensurate with their age.

The floor of the sink cabinet is functional, but moisture damaged.



Components and Conditions Needing Service

The china cabinet door glass is cracked and should be replaced



Valves & Connectors

Functional Components and Conditions

The valves and connectors below the sink are functional. However, they are not in daily use and will inevitably become stiff or frozen.

Faucet

Components and Conditions Needing Service

The faucet is loose, and should be secured.

Trap and Drain

Functional Components and Conditions

The trap and drain are functional.

Garbage Disposal

Functional Components and Conditions

The garbage disposal is functional.

Gas Range

Functional Components and Conditions

The gas range is functional, but was neither calibrated nor tested for its performance.

Gas Cooktop

Functional Components and Conditions

The gas cook top is functional.

Dishwasher

Components and Conditions Needing Service

The dishwasher does not progress through its cycles, and should be evaluated.

Exhaust Fan or Downdraft

Functional Components and Conditions

The exhaust fan or downdraft is functional.

Built-in Microwave

Functional Components and Conditions

The built-in microwave is functional but we did not test it for leakage, which would require a specialized instrument.

Lights

Informational Conditions

The light is functional.

Outlets

Components and Conditions Needing Service

All of the countertop outlets should be upgraded to have ground fault protection, which is mandated by current standards and is an important safety feature.

Hallway

Our evaluation of hallways is identical to that of living space, except that we pay particular attention to safety issues, such as those involving handrails, guardrails, and smoke detectors.

Primary Hallway

No Recommended Service

Informational Conditions

We have evaluated the hallway, and found it to be in acceptable condition.

Attic

In accordance with our standards, we do not attempt to enter attics that have less than thirty-six inches of headroom, are restricted by ducts, or in which the insulation obscures the joists and thereby makes mobility hazardous, in which case we would inspect them as best we can from the access point. In regard to evaluating the type and amount of insulation on the attic floor, we use only generic terms and approximate measurements, and do not sample or test the material for specific identification. Also, we do not disturb or move any portion of it, and it may well obscure water pipes, electrical conduits, junction boxes, exhaust fans, and other components.

Primary Attic

Attic Access Location

Informational Conditions

The attic can be accessed through one of the bedroom closets

Method of Evaluation

Informational Conditions

We evaluated the attic by direct access.

Framing

Informational Conditions

The visible portions of the conventionally stacked roof framing are in acceptable condition, and would conform to the standards of the year in which they were installed.

Ventilation

Informational Conditions

Ventilation is provided by a combination of eave, dormer, turbine, or gable vents, and should be adequate.

Electrical

Informational Conditions

The electrical components that are fully visible appear to be in acceptable condition.

Heat Vents

Informational Conditions

The heat vents appear to be functional.

Exhaust Ducts

Informational Conditions

The visible portions of the exhaust ducts are functional.

Factory-Built Chimney Chase

Informational Conditions

The factory-built chimney has a functional chase surrounding the chimney flue.

Blown-In Cellulose Insulation

Informational Conditions

The attic is adequately insulated, but not necessarily to a maximum standard. The amount of insulation can range from three to eighteen inches, depending upon the climate, the region, and the year in which the residence was constructed.

Bedrooms

In accordance with the standards of practice, our inspection of bedrooms includes the visually accessible areas of walls, floors, cabinets and closets, and includes the testing of a representative number of windows and doors, switches and outlets. We evaluate windows to ensure that they meet light and ventilation requirements and facilitate an emergency exit or egress, but we do not evaluate window treatments, nor move furniture, lift carpets or rugs, empty closets or cabinets, and we do not comment on common cosmetic deficiencies.

Main Bedroom

Location

Informational Conditions

The master bedroom is located in the rear of home.

No Recommended Service

Informational Conditions

We have evaluated the bedroom, and found it to be in acceptable condition.

Bedroom One

Location

Informational Conditions

Bedroom One is located adjacent to master bedroom.

No Recommended Service

Informational Conditions

We have evaluated the bedroom, and found it to be in acceptable condition.

Bedroom Two

Location

Informational Conditions

Bedroom Two is located next to hall bath.

No Recommended Service

Informational Conditions

We have evaluated the bedroom, and found it to be in acceptable condition.

Bedroom Three

Location

Informational Conditions

Bedroom Three is located next to hall bath.

No Recommended Service

Informational Conditions

We have evaluated the bedroom, and found it to be in acceptable condition.

Bathrooms

In accordance with industry standards, we do not comment on common cosmetic deficiencies, and do not evaluate window treatments, steam showers, and saunas. More importantly, we do not leak-test shower pans, which is usually the responsibility of a termite inspector. However, because of the possibility of water damage, most termite inspectors will not leak-test second floor shower pans without the written consent of the owners or occupants.

Main Bathroom

Size and Location

Informational Conditions

The main bathroom is a full, and is located adjacent to the master bedroom.

Doors

Functional Components and Conditions

The door is functional.

Flooring

Informational Conditions

The floor has no significant defects.

Walls & Ceiling

Informational Conditions

The walls and ceiling are in acceptable condition.

Cabinets

Informational Conditions

The cabinets have typical, cosmetic damage.

Sink Countertop

Functional Components and Conditions

The sink countertop is functional.

Sink Faucet Valves & Connectors Trap & Drain

Components and Conditions Needing Service

The mechanical sink stopper is incomplete and should be serviced.



Stall Shower

Functional Components and Conditions

The stall shower is functional.

Toilet & Bidet

Components and Conditions Needing Service

The water shut-off valve for the toilet appears to leak due to the rag under it.



Exhaust Fan

Functional Components and Conditions

The exhaust fan is functional.

Lights

Functional Components and Conditions

The lights are functional.

Outlets

Components and Conditions Needing Service

The outlets should be upgraded to have ground-fault protection.

Second Bathroom

Size and Location

Informational Conditions

The second bathroom is a full, and is located located in the hallway.

Doors

Functional Components and Conditions

The door is functional.

Flooring

Components and Conditions Needing Service

There are missing tiles between the toilet and shower wall



Walls & Ceiling

Informational Conditions

The walls and ceiling are in acceptable condition.

Cabinets

Informational Conditions

The cabinets have typical, cosmetic damage.

Sink Countertop

Functional Components and Conditions

The sink countertop is functional.

Sink Faucet Valves & Connectors Trap & Drain

Functional Components and Conditions

The sink and its components are functional.

Tub-Shower

Components and Conditions Needing Service

There are open grout-joints in the tiles around the tub area and should be sealed to prevent moisture damage.



Toilet & Bidet

Functional Components and Conditions

The toilet is functional.

Exhaust Fan

Functional Components and Conditions

The exhaust fan is functional.

Lights

Functional Components and Conditions

The lights are functional.

Outlets

Components and Conditions Needing Service

The outlets should be upgraded to have ground-fault protection.

Laundry

In accordance with industry standards, we do not test clothes dryers, nor washing machines and their water connections and drainpipes. However, there are two things that you should be aware of. The water supply to washing machines is usually left on, and their hoses can leak or burst under pressure and continue to flow. Therefore, we recommend replacing the rubber hose type with newer braided stainless steel ones that are much more dependable. You should also be aware that the newer washing machines discharge a greater

volume of water than many of the older drainpipes can handle, which causes the water to back up and overflow, and the only remedy would be to replace the standpipe and trap with one that is a size larger.

Laundry Room

No Recommended Service

Informational Conditions

We have evaluated the laundry room and all its components and found it to be in acceptable condition.

Garage

It is not uncommon for moisture to penetrate garages, because their slabs are on-grade. Evidence of this is typically apparent in the form of efflorescence, or salt crystal formations, that result when moisture penetrates the concrete slab or sidewalls. This is a common with garages that are below grade, and some sidewalls are even cored to relieve the pressure that can build up behind them, and which actually promotes drainage through the garage. Also, if there is living space above the garage, that space will be seismically vulnerable. Ideally, the columns and beams around the garage door will be made of structural steel, but in many residences these components are made of wood but could include some structural accessories, such as post-straps and hold-downs, and plywood shear paneling. However, we are not an authority in such matters, and you may wish to discuss this further with a structural engineer. In addition, and inasmuch as garage door openings are not standard, you may wish to measure the opening to ensure that there is sufficient clearance to accommodate your vehicles.

Double-Car Garage

No Recommended Service

Informational Conditions

We have evaluated the garage, and found it to be in acceptable condition.

Garage Door & Hardware

Functional Components and Conditions

The garage door and its hardware are functional.

Automatic Opener

Functional Components and Conditions

The garage door opener is functional.

Pool and Spa

Pools and spas do leak, but without specialized equipment this may be impossible to confirm. However, it could become apparent from secondary evidence during our inspection, which is purely visual. Regardless, the owner or the occupant of a property would be aware that the water level drops regularly and must be topped off, and this should be disclosed. Unusually high water bills could reveal this, but only a pressure test of the pipes, a dye test of cracks, or a geo-phone test of specific areas would confirm it, and any such specialized test is beyond the scope of our service. Therefore, you should ask the sellers to guarantee that the spa does not leak, request to review the water bills for a twelve-month period, or obtain comprehensive insurance to cover such an eventuality.

Pool Only

General Comments

Informational Conditions

The interior finish of pools is rarely perfect and never remains so, and particularly those on pools with colored plasters, and certainly if the chemical balance of the water is not properly maintained. Also, calcium and other minerals does leech through the material and mar the finish. This is equally true of pool tiles, on which mineral scaling is not only common but difficult to remove. Even the harshest abrasives will not remove some scaling, which sometimes has to be removed by bead-blasting, which in turn reduces the luster of the tiles. However, such imperfections have only a cosmetic significance. Similarly, the decks around pools and spas tend to develop cracks that have only a cosmetic significance. The commonest are relatively small, and are often described as being curing fractures. Some of these will contour the outline of the pool, or the point at which the bond beam, or structural wall of the pool, meets the surrounding soil. These too have little structural significance, but some cracks are larger and result from seismic motion, or from settling due to poorly compacted soils, or they confirm the presence of expansive soils, which can be equally destructive, but which should be confirmed by a geo-structural engineer. However, any crack in the shell of a pool or spa should be dye-tested or otherwise evaluated by a specialist.

Enclosure Safety Observations

Components and Conditions Needing Service

The garage side door gives pool access and is required by common safety standards to self-close and include a latch at forty-eight inches, unless an intervening gate conforms to this standard. Garage door does not self-close.

Pool Observations

Functional Components and Conditions

The pool appears to be level and in good condition



Interior Finish

Informational Conditions

The interior finish is fiberglass, which is in acceptable condition. However, all pool surfaces to be kept in good condition need to be maintained with proper filtration, water chemistry and weekly brushing.

Deck & Coping Stones

Informational Conditions

The deck has been resurfaced, probably with a magnesite compound, or some such similar material. However, it is not uncommon for small patches of this material to separate and it should be monitored and maintained.

Expansion Joint

Informational Conditions

The expansion joint is in good condition.

Skimmer

Informational Conditions

The skimmer box and its cover are functional.

Tiles

Functional Components and Conditions

There is scaling, or a build-up of minerals, on the tiles, which is predictable and somewhat unavoidable, but periodical tile cleaning will inhibit the scaling.

Drain Covers

Functional Components and Conditions

The drain cover is in place and is functional

Pool Light


Informational Conditions

The light is functional and has been confirmed to have ground-fault protection. However, for reasons of safety, the circuit should be tested periodically to ensure that its ground fault protection is working.

Diving Board

Components and Conditions Needing Service


The diving board is in poor condition, and should not be used until it has been serviced. However, all diving boards are inherently dangerous, and are directly responsible for serious injuries every year, and must be used responsibly.



Pool Motor

Informational Conditions

The pool motor is an older type with a metal casing, but is functional.



The pool sweep motor is newer and is functional

Supply & Return Lines Etc

Functional Components and Conditions

The supply lines, return lines, and valves are in acceptable condition.

Filter

Functional Components and Conditions

The pool filter is functional.

Inspection Address: 123 Anywhere St, Fresno, CA 93711
Inspection Date/Time: 4/3/2009

REPORT CONCLUSION

123 Anywhere St, Fresno, CA 93711

Congratulations on the purchase of your new home. Inasmuch as we never know who will be occupying or visiting a property, whether it be children or the elderly, we ask you to consider following these general safety recommendations: install smoke and carbon monoxide detectors; identify all escape and rescue ports; rehearse an emergency evacuation of the home; upgrade older electrical systems by at least adding ground-fault outlets; never service any electrical equipment without first disconnecting its power source; safety-film all non-tempered glass; ensure that every elevated window and the railings of stairs, landings, balconies, and decks are child-safe, meaning that barriers are in place or that the distance between the rails is not wider than three inches; regulate the temperature of water heaters to prevent scalding; make sure that goods that contain caustic or poisonous compounds, such as bleach, drain cleaners, and nail polish removers be stored where small children cannot reach them; ensure that all garage doors are well balanced and have a safety device, particularly if they are the heavy wooden type; remove any double-cylinder deadbolts from exterior doors; and consider installing child-safe locks and alarms on the exterior doors of all pool and spa properties.

We are proud of our service, and trust that you will be happy with the quality of our report. We have made every effort to provide you with an accurate assessment of the condition of the property and its components and to alert you to any significant defects or adverse conditions. However, we may not have tested every outlet, and opened every window and door, or identified every minor defect. Also because we are not specialists or because our inspection is essentially visual, latent defects could exist. Therefore, you should not regard our inspection as conferring a guarantee or warranty. It does not. It is simply a report on the general condition of a particular property at a given point in time. Furthermore, as a homeowner, you should expect problems to occur. Roofs will leak, drain lines will become blocked, and components and systems will fail without warning. For these reasons, you should take into consideration the age of the house and its components and keep a comprehensive insurance policy current. If you have been provided with a home protection policy, read it carefully. Such policies usually only cover insignificant costs, such as that of roofer service, and the representatives of some insurance companies can be expected to deny coverage on the grounds that a given condition was preexisting or not covered because of what they claim to be a code violation or a manufacture's defect. Therefore, you should read such policies very carefully, and depend upon our company for any consultation that you may need.

Thank you for taking the time to read this report, and call us if you have any questions or observations whatsoever. We are always attempting to improve the quality of our service and our report, and we will continue to adhere to the highest standards of the real estate industry and to treat everyone with kindness, courtesy, and respect.

Happily yours,

Jerry Schooley

Inspection Address: 123 Anywhere St, Fresno, CA 93711
Inspection Date/Time: 4/3/2009

INDEX

CONFIDENTIAL INSPECTION REPORT	1
GENERAL INFORMATION	2
SCOPE OF WORK	3
REPORT INVOICE	5
Exterior	6
Grading & Drainage	6
House Wall Finish	7
Exterior Components	7
Structural	8
Various Hard Surfaces	9
Structural Elements	9
Raised Foundation	9
Roof/Attic	10
Wood Roof	11
Chimney	11
Family Room Chimney	12
Plumbing	13
Potable Water Supply Pipes	13
General Gas Components	14
Gas Water Heaters	14
Waste & Drainage Systems	15
Electrical	16
Main Panel	16
Heat and Air Conditioning	17
HVAC Package Systems	18
Living Areas	19
Indoor Environmental Issues	19
Main Entry	20
Living Room	20
Family Room	20
Kitchen	20
Kitchen	20
Hallway	22
Primary Hallway	22
Attic	23
Primary Attic	23
Bedrooms	24
Main Bedroom	24
Bedroom One	24
Bedroom Two	24
Bedroom Three	24
Bathrooms	25
Main Bathroom	25
Second Bathroom	26
Laundry	27
Laundry Room	28
Garage	28
Double-Car Garage	28
Pool and Spa	28

Inspection Address: 123 Anywhere St, Fresno, CA 93711
Inspection Date/Time: 4/3/2009

Pool Only	29
REPORT CONCLUSION	32
INDEX	33

Perfect Inspections

5668 N Prospect Ave Fresno CA 93711
Tel: 559 352-6941 Fax: 559 438-8001 Mobile: 559 352-6941
Email Address: jerry_schooley@hotmail.com

Property Address: 123 Anywhere St, Fresno, CA 93711
Inspection Date: 4/3/2009

Jo Smith
123 Anywhere St
Fresno, CA. 93711

Dear Jo Smith:

Thank you for hiring Perfect Inspections to be of service. We hope that you were pleased with the quality of our service, and that you would recommend us to others. Please read the report carefully, and call us with any questions that you might have. We remain your consultant indefinitely, and would be happy to assist you in any way that we can. We sincerely hope that you and your family will be happy and healthy in your new home.

Sincerely,

Jerry Schooley